

0966445-092801




Fig.1

10966445-092801




Fig.2




Fig.3




Fig. 4A




Fig. 4B




Fig.5




Fig.6






Fig.7




**Fig. 8**






**Fig. 9A**



**Fig. 9B**



**Fig. 9C**

SCAN DIRECTION  
OF LASER ANNEAL  
↓




Fig. 10A




Fig. 10B






Fig.11



**Fig. 12**



**Fig. 13**

**Fig. 14**

108260" 5499660




Fig. 15A




Fig. 15B




Fig. 16A




Fig. 16B



0966445.092801




Fig. 17




Fig. 18

096445 092801  
T08260" 54499660




Fig. 19




Fig. 20